

# Supplement

## Characteristics of Housing in Darkale Rural Settlement, Soma, Manisa

Ayşen Etlacakuş<sup>1\*</sup>, Mine Hamamcıoğlu Turan<sup>1</sup>

<sup>1</sup> Department of Conservation and Restoration of Cultural Heritage, Izmir Institute of Technology, 35430 Gülbahçe, Izmir, Türkiye

\* Corresponding author, e-mail: [aysenetlacakus@iyte.edu.tr](mailto:aysenetlacakus@iyte.edu.tr)



Fig. S1 (a) Site plan and photos, (b) spatial analysis, (c) alteration analysis of current of house number 8



Fig. S2 (a) Site plan and photos, (b) spatial analysis, (c) alteration analysis of current of house numbered 13



Fig. S3 (a) Site plan and photos, (b) spatial analysis, (c) alteration analysis of current of house numbered 45






Fig. S4 (a) Site plan and photos, (b) spatial analysis, (c) alteration analysis of current of house numbered 152



Fig. S5 (a) Site plan and photos, (b) spatial analysis, (c) alteration analysis of current of house numbered 43